HOW TO ACTIVATE

2K CLEAR



@thespraysource

FLIP THE CAN.
WORK THE BOTTOM.




REMOVE THE PLUG.
PULL OFF THE METAL RING

STEP 1



@thespraysource

PUT THE RING THROUGH THE LUG ON THE BAR



@thespraysource

THE SPRAY SOURCE

PULL OUT AND TURN 360.





TWO COMPONENTS
ONE SPRAY CAN

@thespraysource

SHAKE HARD. 45 TO 60 SECONDS.

45 TO 60 SECONDS



@thespraysource



POT LIFE STARTS NOW.

ABOUT 24 HOURS

Wear a paint-rated respirator, gloves and goggles



USE WITHIN POT LIFE

AVOID HEAT AND SUN.

@thespraysource

SPRAY 2 TO 3 MEDIUM WET COATS

FULL PANEL, NEVER POOLING



RECOAT WHEN THE MASKING FEELS FINGERPRINTY.

ABOUT 8 TO 10 MIN.



@thespraysource

CLEAR THE NOZZLE UPSIDE DOWN.

SHOP 2K CLEAR.



@thespraysource